

## S SPLICE

NEMA 1		NEMA 2		NEMA 3		NEMA 20C	
2 x <b>HS820</b> Hex Screws supplied per Splice Plate.		4 x <b>SB</b> Splice Bolts and <b>CN</b> Splice Nuts required per Splice Plate.		8 x <b>SB</b> Splice Bolts and <b>CN</b> Splice Nuts required per Splice Plate.		8 x <b>SB</b> Splice Bolts and <b>CN</b> Splice Nuts required per Splice Plate.	
N1SH	A	N2SH	A	N3SH	A	N20C-FR70SH	B
N1SS	B	N2SS	B	N3SS	B	N20CSS	C

**Example**

Use in pairs  
Nema 2 shown

FASTENERS

STRUT SYSTEMS

## VS VERTICAL SPLICE

NEMA 1		NEMA 2		NEMA 3		NEMA 20C	
2 x <b>HS820</b> Hex Screws supplied per Splice Plate.		4 x <b>SB</b> Splice Bolts and <b>CN</b> Splice Nuts required per Splice Plate.		8 x <b>SB</b> Splice Bolts and <b>CN</b> Splice Nuts required per Splice Plate.		8 x <b>SB</b> Splice Bolts and <b>CN</b> Splice Nuts required per Splice Plate.	
N1VSH	A	N2VSH	A	N3VSH	A	N20CVSH	B
N1VSS	B	N2VSS	B	N3VSS	B	N20CVSS	C

**Example**

Use in pairs  
Nema 2 shown

CABLE SUPPORTS

## HS HORIZONTAL SPLICE

NEMA 1		NEMA 2		NEMA 3		NEMA 20C	
2 x <b>HS820</b> Hex Screws supplied per Splice Plate.		4 x <b>SB</b> Splice Bolts and <b>CN</b> Splice Nuts required per Splice Plate.		8 x <b>SB</b> Splice Bolts and <b>CN</b> Splice Nuts required per Splice Plate.		8 x <b>SB</b> Splice Bolts and <b>CN</b> Splice Nuts required per Splice Plate.	
N1HSH	A	N2HSH	A	N3HSH	A	N20CHSH	B
N1HSS	B	N2HSS	B	N3HSS	B	N20CHSS	C

**Example**

Use in pairs  
Nema 2 shown

FIRERATED

## SHB HANGING SPLICE BRACKET (NEMA 1 PRODUCT ONLY)

2 x **HS820** Hex Screws supplied per Splice Plate.

**Example**

Use in pairs

Threaded Rod Size	Nema 1 only	
	Part No.	Service Guide
10	N1SHB10H	A
12	N1SHB12H	D

**D** ALSO AVAILABLE IN STAINLESS STEEL AS MADE TO ORDER (MTO).

PIPE SUPPORTS