



⚠️ DANGER / 危险
HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH
 Disconnect all power before servicing equipment. Failure to follow these instructions will result in death or serious injury.
 电击、爆炸或弧闪的危险
 在此电力设备上进行操作时，请先断开所有电源。不遵循上述说明将导致人员伤亡。

| Ø4 mm | | | Ø3 mm | | | |
|----------------------------|--------------------------|--------------------------|------------------------------|-------------------------------|-----------------------------|-----------------------------|
| GV2ME●●3 / GV2RT●●3 | | | GVAN●●3 | | GVAE●●3 | |
| | | | | | | |
| 1...2,5 mm ² | 1...4 mm ² | 1...4 mm ² | 0,5...1,5 mm ² | 0,75...2,5 mm ² | 1...2,5 mm ² | 0,34...1 mm ² |
| AWG 10 - 18 CU 75°C | | | AWG 14 - 18 CU 60 / 75°C | | AWG 18 - 20 CU 60 / 75°C | |
| STRIP = 3/8 " 剥线长度=3/8" | | | STRIP = 3/8 " 剥线长度=3/8" | | STRIP = 3/8 " 剥线长度=3/8" | |



www.se.com/site/home

1672546 (GV2ME●●3)

Schneider Electric Industries SAS
 35, rue Joseph Monier
 92506 Rueil Malmaison
 France
 GV2ME●●3, GV2RT●●3
 W9 1645883 0211 A07
 05 - 2021

